



photo 1: Facing south at the beginning of the access road.



photo 2: Further south along the road, a second cattle guard is installed.



photo 3: Facing south along the access road. A soil borrow areas is being used off of the road.



photo 4: Facing toward the borrow area.



photo 5: Facing south, culverts are installed and material from the borrow area is placed over the culverts.



photo 6: Further south along the road, another cattle guard



photo 7: Facing south toward the location. Construction of the location has begun.



photo 8: Topsoil is being pushed toward the west side of the location.



photo 9: Facing south toward topsoil pile. Surface roughening has occurred around the perimeter.



photo 10: Facing northwest toward the location.