

**Inspection Photos**  
**Location Name: Walcker AC17-64HN**  
**API: 05-123-35071**



**Photo 1: Location, looking SE**



**Photo 2: Wellhead, looking SE**



**Inspection Photos**  
**Location Name: Walcker AC17-64HN**  
**API: 05-123-35071**



**Photo 3: Stained soil at wellhead**



**Photo 4: Stained soil at Ajax exhaust**



**Inspection Photos**  
**Location Name: Walcker AC17-64HN**  
**API: 05-123-35071**



**Photo 5: Stained soil at Ajax engine**

**Photo 2: Wellhead, looking SE**