

Inspection Photos
Location Name: Ramirez AC 29-72HN
API: 05-123-34975



Photo 1: Wellhead, looking SE



Photo 2: Location, looking NE

Inspection Photos
Location Name: Ramirez AC 29-72HN
API: 05-123-34975



Photo 3: Stained soil at wellhead



Photo 4: Stained soil at engine exhaust