

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/10/2017

Submitted Date:

04/12/2017

Document Number:

685302566

**FIELD INSPECTION FORM**

Loc ID 312052 Inspector Name: St John, William (Cal) On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 19160  
Name of Operator: CONOCO PHILLIPS COMPANY  
Address: P O BOX 2197  
City: HOUSTON State: TX Zip: 77252-

**Findings:**

29 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Busse, Dollie	505-324-6104	dollie.l.busse@conocophillips.com	<a href="#">SW Inspection Reports</a>
Prasanna, Sonu	832-486-2299	Sonu.Prasanna@conocophillips.com	<a href="#">SW Inspection Reports</a>
Walker, Crystal	505-326-9837	Crystal.Walker@cop.com	<a href="#">SW Inspection Reports</a>
Brock, Christine		Christine.Brock@conocophillips.com	<a href="#">SW Inspection Reports</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216500	WELL	PR	01/01/2003	GW	067-08106	ANIMAS 34-10 36-1	PR
297003	WELL	PR	02/01/2011	GW	067-09593	ANIMAS 34-10 36-1A	PR
297004	WELL	PR	02/01/2011	GW	067-09594	ANIMAS 34-10 36-2A	SI

**General Comment:**

[Bradenhead testing and location inspection.](#)

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Dirt and gravel two track road.		
Corrective ActionL			Date:

Overall Good:

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Free standing framed sign located at wellhead.		
Corrective Action:			Date:
Type	CONTAINERS		
Comment:	Labels on lube oil tank.		
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	Operator contact information posted on wellhead sign.		
Corrective Action:			Date: _____

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	SEPARATOR		
Comment:	Steel post and pole barrier.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Steel post and pole barrier.		
Corrective Action:			Date:
Type	PUMP JACK		
Comment:	Safety rails.		
Corrective Action:			Date:

<b>Equipment:</b>			corrective date
Type: Flow Line	# 3		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 3		
Comment:	Wellhead.		
Corrective Action:			Date:

Type: Pig Station	# 1		
Comment:			
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Solar panel array.		
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Water can and valve set.		
Corrective Action:			Date:
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Lube oil tank on spill prevention.		
Corrective Action:			Date:
Type: Gas Meter Run	# 3		
Comment:			
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:	Natural gas motor.		
Corrective Action:			Date:
Type: Vertical Heated Separator	# 3		
Comment:	One building with three separator systems.		
Corrective Action:			Date:
Type: Ancillary equipment	# 2		
Comment:	Telemetry equipment.		
Corrective Action:			Date:
Type: Deadman # & Marked	# 10		
Comment:			
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Cathodic protection equipment.		
Corrective Action:			Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

<b>Inspected Facilities</b>			
Facility ID: <u>216500</u>	Type: <u>WELL</u>	API Number: <u>067-08106</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
<b>Producing Well</b>			
Comment: <span style="color: blue;">PR - Review of electronic well file indicates last reported production as January 2017.</span>	Corrective Action:		Date:
<b>BradenHead</b>			
Comment: <span style="color: blue;">Witnessed Braden Head Testing. Initial BH 20.5 PSI, Casing 57 PSI, Tubing 54 PSI. Instantaneous BH 0.0 PSI.</span>	Corrective Action:		Date:
Facility ID: <u>297003</u>	Type: <u>WELL</u>	API Number: <u>067-09593</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
<b>Producing Well</b>			
Comment: <span style="color: blue;">PR - Review of electronic well file indicates last reported production as January 2017.</span>	Corrective Action:		Date:
<b>BradenHead</b>			
Comment: <span style="color: blue;">Witnessed Braden Head Testing. Initial BH 17.0 PSI, Casing 61 PSI, Tubing 59 PSI. Instantaneous BH 0.0 PSI.</span>	Corrective Action:		Date:
Facility ID: <u>297004</u>	Type: <u>WELL</u>	API Number: <u>067-09594</u>	Status: <u>PR</u> Insp. Status: <u>SI</u>
<b>Idle Well</b>			
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned    Reminder: <u>FLOWLINE AVAILABLE-CONNECTED</u>			
Comment: <span style="color: blue;">PR - Review of electronic well file indicates last reported production as April 2016. The well status is reported as SI since May 2017.</span>	Corrective Action:		Date:
<b>BradenHead</b>			
Comment: <span style="color: blue;">Witnessed Braden Head Testing. Initial BH 22.1 PSI, Casing 20 PSI, Tubing 0.0 PSI. Instantaneous BH 0.0 PSI.</span>	Corrective Action:		Date:

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: Location surrounded by open grazing land.

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_  
 1003c. Compacted areas have been cross ripped? \_\_\_\_\_  
 1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_  
 Cuttings management: \_\_\_\_\_  
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_  
 Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

RESTORATION AND REVEGETATION

Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

1003e. INTERIM VEGETATION TRANSECT  
 TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_  
 TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_  
 TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_  
 VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment

Corrective Action

Date \_\_\_\_\_

Overall Interim Reclamation

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment:

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

1004.d. FINAL VEGETATION TRANSECT  
 TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_  
 TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_  
 TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_  
 VEGETATIVE COVER \_\_\_\_\_

Comment:

Corrective Action:

Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location  Multi-Well Location

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	Lube oil tank on spill prevention.
Gravel	Pass	Gravel	Pass			

Comment: [Stormwater BMPs appear to be functioning at time of inspection.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685302614	Wellhead sign for 067 09395.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4126089">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4126089</a>
685302615	Location overview from pump jack looking W.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4126090">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4126090</a>
685302616	Wellhead sign for 067 08106.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4126091">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4126091</a>
685302617	Wellhead sign for 067 09594.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4126092">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4126092</a>