



**photo 1:** Facing north toward the location. Red circle indicates photo 2 shown below.



**photo 2:** Stained soils were found at center of the location adjacent to the road. Area is also circled red in the above photo.





**photo 3:** Guyline anchor remains at the northwest corner of the location.



**photo 4:** The soil around the northwest guyline anchor appears to have oil stained soils.