



photo 1: Facing south toward the location.



photo 2: Facing north at the location. There is miscellaneous debris throughout the site.



photo 3: There are pieces of concrete and oil stained soils throughout the site.



photo 4: Photo shows wooden block and oil stained soils.