

FORM  
INSPRev  
X/15

## State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/10/2017

Submitted Date:

04/12/2017

Document Number:

685302563

### FIELD INSPECTION FORM

Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection   
326060 \_\_\_\_\_ St John, William (Cal) \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 19160  
 Name of Operator: CONOCO PHILLIPS COMPANY  
 Address: P O BOX 2197  
 City: HOUSTON State: TX Zip: 77252-

**Findings:**

- 17 Number of Comments  
2 Number of Corrective Actions  
 Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Brock, Christine		Christine.Brock@conocophillips.com	<a href="#">SW Inspection Reports</a>
Walker, Crystal	505-326-9837	Crystal.Walker@cop.com	<a href="#">SW Inspection Reports</a>
Busse, Dollie	505-324-6104	dollie.l.busse@conocophillips.com	<a href="#">SW Inspection Reports</a>
Prasanna, Sonu	832-486-2299	Sonu.Prasanna@conocophillips.com	<a href="#">SW Inspection Reports</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215798	WELL	PR	09/18/1990	GW	067-07403	BONDAD 33-10 COM 104	PR

**General Comment:**

Bradenhead testing and location inspection. This inspection does not remove requirement to complete any open corrective actions from previous inspections. Inspection report contains corrective action and comments. See Tanks and Berms section of report for additional details. See link at end of report for path to downloadable pictures.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Dirt and gravel two track road.		
Corrective ActionL			Date:

Overall Good:

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:	Labels directly on tank.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Free standing framed sign located at wellhead.		
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	Operator contact information posted on wellhead sign.		
Corrective Action:			Date: _____

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Telemetry equipment		
Corrective Action:			Date:
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		

Comment:	Wellhead.	Date:	
Corrective Action:		Date:	
Type: Flow Line	# 1		
Comment:		Date:	
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	STEEL AST		
Comment:	Tank is missing 2 gauge hatch covers and has another opening large enough for wildlife entry point.				
Corrective Action:	Repair or replace hatches and seal opening to prevent wildlife from entering tank to comply with Rule 201.				Date: 05/13/2017

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	UNKOWN tank not labeled.
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Insufficient	Inadequate
Comment:	Grass is growing inside bermed area.			
Corrective Action:	Repair or install berms or other secondary containment to comply with Rule 605.a.(4).			Date: 05/13/2017

**Venting:**

Yes/No	NO	Date:	
Comment:		Date:	
Corrective Action:		Date:	

**Flaring:**

Type		Date:	
Comment:		Date:	
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 215798 Type: WELL API Number: 067-07403 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR - Review of electronic well file indicates last reported production as January 2017.

Corrective Action:

Date:

**BradenHead**

Comment: Witnessed Braden Head Testing. Initial BH 1.7 PSI, Casing 109 PSI, Tubing 17 PSI. Instantaneous BH 0.1 PSI.

Corrective Action:

Date:

**Completion**

Operation:

Date Flowback:

Contractor:

Comment:

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: Shared location. Location is surrounded by irrigated pasture.

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_  
 1003c. Compacted areas have been cross ripped? \_\_\_\_\_  
 1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_  
 Cuttings management: \_\_\_\_\_  
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_  
 Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

RESTORATION AND REVEGETATION

Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

1003e. INTERIM VEGETATION TRANSECT  
 TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_  
 TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_  
 TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_  
 VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment

Corrective Action

Date \_\_\_\_\_

Overall Interim Reclamation

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment:

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

1004.d. FINAL VEGETATION TRANSECT  
 TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_  
 TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_  
 TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_  
 VEGETATIVE COVER \_\_\_\_\_

Comment:

Corrective Action:

Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location  Multi-Well Location

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401257642	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4122917">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4122917</a>
685302610	Wellhead sign for 067 07403	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4122881">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4122881</a>
685302611	Tank missing hatch cover.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4122883">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4122883</a>
685302612	Tank missing hatch and opening at top of tank.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4122885">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4122885</a>
685302613	Grass growing inside berms around tank.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4122887">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4122887</a>