

Construction and Stormwater Inspection

April 12, 2017

Operator: BURLINGTON RESOURCES OIL & GAS LP- #26580

Location ID: 443722

Arapahoe County, CO

SWSW Section 2 T4S R65W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Prosper Farms 4-65 2-1 /4AH
Location ID: 443722



Photo 1. Photo taken from the access point off North Haysmount Road, facing East. Topsoil has been stripped off from the access road and subsoil material is being used to build up the access road. Temporary stormwater BMP installed along the north, east, and south of the location in the form of a filtrex wattle.



Photo 2. Photo taken from the access road, facing Northeast. Topsoil has been stripped off from the access road and subsoil material is being used to build up the access road. Temporary stormwater BMP installed along the north, east, and south of the location in the form of a filtrex wattle.

Inspection Photos
Location Name: Prosper Farms 4-65 2-1 /4AH
Location ID: 443722



Photo 3. Photo taken along the northern location perimeter and the intersection of the eastern access point, facing North. Photo illustrates swale area where potential stormwater runoff would likely flow.



Photo 4. Photo taken from the eastern perimeter of the location, facing South. Topsoil is in the process of being salvaged. Topsoil did not appear to be evenly salvaged throughout portions of the location. Temporary stormwater BMP installed along the north, east, and south of the location in the form of a filtrex wattle.

Inspection Photos

Location Name: Prosper Farms 4-65 2-1 /4AH

Location ID: 443722



Photo 5. Photo taken from the southern perimeter of the location, facing West. Topsoil is in the process of being salvaged. Topsoil did not appear to be evenly salvaged throughout portions of the location. Temporary stormwater BMP installed along the north, east, and south of the location in the form of a filtrex wattle.



Photo 6. Photo taken from the southern location, facing Northwest towards the topsoil stockpile. Topsoil did not appear to be evenly salvaged throughout portions of the location.

Inspection Photos

Location Name: Prosper Farms 4-65 2-1 /4AH

Location ID: 443722



Photo 7. Photo taken from the western perimeter of the location, facing North. Ditch BMP has been installed along the western side of the topsoil stockpile.