

Inspection Photos

04/13/2017

Operator: Rampart Energy Co #5685

Location ID: 387264

Inspection Doc. Number: 682501891

Logan County, CO

NWSE Section 20 T6N R54W

Aaron Trujillo

Reclamation Specialist

COGCC



Inspection Photos
Operator: Rampart Energy
Location ID: 387264



Photo 1: Photo taking from the concrete pumping unit, facing south. This needs to be removed and the area reclaimed.



Photo 2: Photo taking from the concrete pumping unit, facing south. Photo shows that a thin layer of soil has accumulated on top of unit, after a little scraping the concrete base was evident. This needs to be removed and the area reclaimed.

Inspection Photos
Operator: Rampart Energy
Location ID: 387264



Photo 3: Photo taken from the east end of where the concrete pumping unit remains. Photo shows pipe still remaining and sticking out of the ground. This will need to be removed.



Photo 4: Photo taken from the fence corner east of the concrete pumping unit, facing south. Photo shows pipe still remaining and sticking out of the ground. This will need to be removed.

Inspection Photos
Operator: Rampart Energy
Location ID: 387264



Photo 5: Photo taken from the east of the concrete pumping unit. Photo shows pipe remaining and sticking out of ground. Likely gathering/flow line. This needs to be removed and area reclaimed.



Photo 6: Photo taken from the north end of the location, facing west. Photo shows additional concrete structures remaining in the immediate area. Tank likely surface owners, it is unclear if the concrete structures area related to the O&G location. Surface owner appears to be storing equipment/debris in area.

Inspection Photos
Operator: Rampart Energy
Location ID: 387264




Photo 7: 2016 aerial imagery. Photo shows actual well location compared to coordinates on well file based on footages. Photo also shows area where the flow/gathering lines remain and are visible above ground (red line) and areas where pipe are sticking out of the ground (yellow arrows)