

Inspection Photos

04/17/2017

Operator: Adkins Oil / COGCC

Location ID: 393754

Inspection Doc. Number: 682501907

Arapahoe County, CO

NWNW Section 22 T5S R62W

Aaron Trujillo

Reclamation Specialist

COGCC



Inspection Photos
Operator: Adkins / COGCC
Location ID: 393754



Photo 1: Photo taken from the fence line east of the well location, facing west. Photo shows reclamation in process along access road.



Photo 3: Photo taken from the fence line east of the well location, facing east. Photo shows reclamation in process along access road.

Inspection Photos
Operator: Adkins / COGCC
Location ID: 393754



Photo 3: Photo taken from the southeast corner of the well location, facing northwest. Photo shows the reclamation process of the well. Area of the well does not appear to be progressing as well as reclamation areas outside of fence. Will continue to monitor the reclamation to evaluate progression.



Photo 4: Photo taken from the southeast corner of the well location, facing west. Photo shows the reclamation process of the well. Area of the well does not appear to be progressing as well as reclamation areas outside of fence. Will continue to monitor the reclamation to evaluate progression. .

Inspection Photos
Operator: Adkins / COGCC
Location ID: 393754



Photo 5: Photo taken from within fenced reclamation area. Photo shows two rosettes found within reclamation area. The rosette to the right had large leaves covered in fine “grayish” hairs, features similar to that found with Scotch thistle. The rosette to the left had features similar to that found with Canada thistle rosettes. Will need to monitor, until more pronounced and defining features of the plant become evident and allow for a more accurate ID. Hat used for reference.

Inspection Photos
Operator: Adkins / COGCC
Location ID: 393754



Photo 6: Photo taken from the south end of the fenced reclamation area. Photo shows areas of the reclamation area where desirable plant germination is evident, however in low numbers compared to other areas of the reclamation area. Species such as Amaranth, Salsola, and Panicum capillare appeared prevalent.



Photo 7: Photo taken from the north end of the fence reclamation. Photo shows areas of the reclamation where desirable plant germination is evident