

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/11/2017

Submitted Date:

04/14/2017

Document Number:

679700425

FIELD INSPECTION FORM

Loc ID 332705 Inspector Name: ALLISON, RICK On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10071
 Name of Operator: BARRETT CORPORATION* BILL
 Address: 1099 18TH ST STE 2300
 City: DENVER State: CO Zip: 80202

Findings:

- 3 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Inspections, Field		COGCC_FIR@billbarrettcop.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
291415	WELL	PR	01/13/2012	GW	123-26053	70 RANCH 4-6-20	EI
449977	SPILL OR RELEASE	AC			-	70 Ranch 4-6-20 flowline	EI

General Comment:

[COGCC Environmental inspection spill ID 449977 / 70 Ranch 4-6-20 flowline](#)

Inspected Facilities

Facility ID: 291415 Type: WELL API Number: 123-26053 Status: PR Insp. Status: EI

Facility ID: 449977 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

Environmental

Waste Management:

Type	Management	Condition	GPS (Lat)	(Long)
Oily Soil	Piles	Adequate		
Comment	20-30 yards of hydrocarbon impacted soil is stockpiled pending disposal			
Corrective Action				Date: _____

Spill/Remediation:

Comment: Excavation was open at wellhead and repaired flowline visible. Sidewalls of excvaton do not appear impacted. Operator is waiting on analytical results to backfill excavation.

Corrective Action: Date: _____

Emission Control Burner (ECB): _____

Comment:

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401259575	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4124243
679700426	Photo of excavation and repaired flowline	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4124229
679700427	Photo of excavation and repaired flowline	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4124230