

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/20/2017

Submitted Date:

04/21/2017

Document Number:

674901609**FIELD INSPECTION FORM**

Loc ID 325163 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 26625Name of Operator: ELM RIDGE EXPLORATION COMPANY LLCAddress: 12225 GREENVILLE AVE STE 950City: DALLAS State: TX Zip: 75243-**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Lindeman, Terry	(505) 632-3476 Ext 210	tlindeman@elmridge.net	
Fischer, Alex		alex.fischer@state.co.us	
Archuleta, Amy		aarchuleta@elmridge.net	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214173	WELL	PR	11/14/1957	GW	067-05493	FASSETT MESAVERDE UNIT 1	EI

General Comment:

On April 20, 2017 COGCC SW EPS Jim Hughes conducted a follow up environmental field inspection of the Elm Ridge Exploration Co. Fassett Mesaverde #1. For the most recent field inspection report for this facility, please refer to document #674901469. Corrective actions required by that document have been completed.

LocationOverall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:	Free standing sign near well head.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	PW vessel is labeled with contents, volume, and NFPA placard.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

			corrective date
Type: Horizontal Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLS	STEEL AST		37.122900,-107.762789
Comment:					
Corrective Action:		Date:			

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	20 bbl.
Other (Type)	

Berms

Inspector Name: Hughes, Jim

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:	Secondary containment berm has been rebuilt with adequate capacity.				
Corrective Action:				Date:	
Venting:					
Yes/No					
Comment:					
Corrective Action:				Date:	
Flaring:					
Type					
Comment:					
Corrective Action:				Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
On April 20, 2017 COGCC SW EPS Jim Hughes conducted a follow up environmental field inspection of the Elm Ridge Exploration Co. Fassett Mesaverde #1. For the most recent field inspection report for this facility, please refer to document #674901469. Corrective actions required by that document have been completed. The secondary containment berm around the produced water tank has been rebuilt with adequate capacity. The location has been bladed.	hughesj	04/21/2017

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674901610	Fassett MV #1 production equipment and well head.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4129206
674901611	Location has been bladed.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4129207
674901612	Secondary containment berm has been rebuilt.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4129208