

FORM  
INSPRev  
X/15

## State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/20/2017

Submitted Date:

04/21/2017

Document Number:

674901613

### FIELD INSPECTION FORM

Loc ID 311901 Inspector Name: Hughes, Jim On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 26625  
 Name of Operator: ELM RIDGE EXPLORATION COMPANY LLC  
 Address: 12225 GREENVILLE AVE STE 950  
 City: DALLAS State: TX Zip: 75243-

**Findings:**

- 9 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Lindeman, Terry	505-632-8048 EXT 210	tlindeman@elmridge.net	<a href="#">SW Inspection Reports</a>
Archuleta, Amy		aarchuleta@elmridge.net	<a href="#">All SW Inspections</a>
Fischer, Alex		alex.fischer@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216311	WELL	SI	02/01/2017	GW	067-07917	FASSETT GAS UNIT 2	EI

**General Comment:**

On April 20, 2017 COGCC SW EPS Jim Hughes conducted a follow up environmental field inspection of the Elm Ridge Exploration Co. Fassett GU #2. For the most recent field inspection report of this facility, please refer to document #674901474. Corrective actions noted in that document have been completed.

**Location**

Overall Good:

**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	Produced water tanks are labeled with contents, volume, and NFPA placards.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Free standing sign near well head.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: <input type="text"/>

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type	#		corrective date
Ancillary equipment	# 1		
Comment:	Solar panel		
Corrective Action:		Date:	
Ancillary equipment	# 1		
Comment:	Transfer pump and shack.		
Corrective Action:		Date:	
Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Vertical Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	300 BBLS	STEEL AST		37.121696,-107.762877
Comment:					
Corrective Action:		Date:			

**Paint**

Condition	Adequate
Other (Content)	<input type="text"/>

Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment: <span style="color: blue;">Secondary containment berm has been rebuilt.</span>					
Corrective Action:				Date:	

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 216311 Type: WELL API Number: 067-07917 Status: SI Insp. Status: EI

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
On April 20, 2017 COGCC SW EPS Jim Hughes conducted a follow up environmental field inspection of the Elm Ridge Exploration Co. Fassett GU #2. For the most recent field inspection report of this facility, please refer to document #674901474. Corrective actions noted in that document have been completed. The secondary containment berm for the tank battery has been rebuilt with sufficient capacity.	hughesj	04/21/2017

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674901614	Transfer pump shack and tank battery.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4129209">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4129209</a>
674901615	Secondary containment berm has been rebuilt.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4129210">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4129210</a>