

FORM
INSPRev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/24/2017

Submitted Date:

04/24/2017

Document Number:

679700428

FIELD INSPECTION FORM

Loc ID 429169 Inspector Name: ALLISON, RICK On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10261
 Name of Operator: BAYSWATER EXPLORATION AND PRODUCTION LLC
 Address: 730 17TH ST STE 610
 City: DENVER State: CO Zip: 80202

Findings:

- 3 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Miller, Meagan	832-746-8446	mmiller@bayswater.us	
Barbula, Don	303-912-4213	dbarbula@bayswater.us	
Axelson, John		john.axelson@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
429170	WELL	PR	02/10/2014	OW	123-35725	BALDRIDGE 7-1	EI

General Comment:

[COGCC Environmental Inspection for spill reported to COGCC on 4/22/2017](#)

Inspected Facilities

Facility ID: 429170 Type: WELL API Number: 123-35725 Status: PR Insp. Status: EI

Environmental

Waste Management:

Type	Management	Condition	GPS (Lat)	(Long)	
Oily Soil	Piles				
Comment	A 4-6 cubic yard stockpile of impacted pad road base was stockpiled within a temporary earthen containment berm.				
Corrective Action				Date:	

Spill/Remediation:

Comment:	COGCC met Operator onsite in response to spill that occurred the evening of 4/21/2017 and was reported to COGCC on 4/22/2017. Operator stated that Severance Fire Department responded to a call from the public and alerted Operator to the release. Separator disc had ruptured releasing oil/condensate from the pad to the west across a grass pasture just upgradient of drain tile discharge area. COGCC did not observe impacts to surface water. Vegetation upgradient of surface water was impacted. Soil beneath the vegetation did not appear impacted. Operator stated that a residence approximately 450 feet west of the release point was impacted and had been washed. Operator is communicating with resident. Operator has placed absorbent booms downgradient of vegetation and in the drain tile discharge area and was monitoring for a sheen. Operator stated that no sheen has been observed. COGCC did not observe a sheen or liquid hydrocarbons on or near the surface water and drain tile discharge area during the inspection.		
Corrective Action:	Operator is directed to continue to remove impacts from the vegetated area and the residence to the west in a timely manner to prevent precipitation or stormwater from impacting downgradient surface water. Corrective Action Date in this inspection is the inspection date to indicate the need for immediate and continued response to remove the impacts. Operator is directed to report all corrective actions through the eForm 19 Spill Report.		Date: 04/24/2017

Emission Control Burner (ECB): _____

Comment:

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679700429	Impacted pasture from pad looking west	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4130708
679700430	Storm water ponded in containment on pad	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4130709
679700431	Oily waste stockpile	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4130710
679700432	Impacted pasture from west looking east	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4130711
679700433	Drain tile discharge ppint	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4130712