

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/21/2017

Submitted Date:

04/24/2017

Document Number:

685302759**FIELD INSPECTION FORM**Loc ID 334057 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 56680Name of Operator: MERRION OIL & GAS CORPAddress: 610 REILLY AVENUECity: FARMINGTON State: NM Zip: 87401**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
-
- ☐
- FOLLOW UP INSPECTION REQUIRED
-
- ☒
- NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Thompson, Philana	(505) 324-5300	pthompson@merrion.bz	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
284872	WELL	PR	01/01/2016	GW	067-09173	ANTARES 1	PR
292046	WELL	PR	10/15/2007	GW	067-09388	SHAULA 1	PR

General Comment:[See link at end of report for path to downloadable pictures.](#)

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type OTHER

Comment: Stained soil - Corrective action completed.

Corrective Action: Date: Overall Good: ☐**Spills:**

Type Area Volume

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	Open Top		,
Comment: 45 BBL open top tank with steel mesh top.					
Corrective Action: <input type="text"/>					Date: <input type="text"/>

Paint

Condition Adequate

Other (Content)

Other (Capacity) 45 BBLS

Other (Type)

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment: Corrective action completed.				
Corrective Action: <input type="text"/>				Date: <input type="text"/>

Venting:

Yes/No

Comment: Corrective Action: Date: **Flaring:**

Type	<input type="text"/>
Comment:	<input type="text"/>
Corrective Action:	Date: <input type="text"/>

Inspected Facilities									
Facility ID:	<u>284872</u>	Type:	<u>WELL</u>	API Number:	<u>067-09173</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Facility ID:	<u>292046</u>	Type:	<u>WELL</u>	API Number:	<u>067-09388</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	Berms around tank.

Comment: [Corrective action completed.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685302804	Wellhead sign for 067 09173.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4130772
685302805	Wellhead sign for 067 09388.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4130773
685302806	Cleaned up soil and gravel.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4130774
685302807	Tank with berms.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4130775