

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/26/2017

Submitted Date:

04/26/2017

Document Number:

667601588**FIELD INSPECTION FORM**

Loc ID 336032 Inspector Name: Kraich, Adam On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 10454Name of Operator: PETROSHARE CORPORATIONAddress: 9635 MAROON CIRCLE #400City: ENGLEWOOD State: CO Zip: 80112**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**18 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Lloyd, Bill		blloyd@petrosharecorp.com	Operations Manager
Witsell, Fred	303-500-1168	fwitsell@petrosharecorp.com	
Powell, Harold	(918)-774-3120	hpowell@petrosharecorp.com	Field Op Manager

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
203827	WELL	PR	03/31/2008	GW	001-09387	STONEHOCKER 32-8	PR

**General Comment:**

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Tracking pad at entrance off Quebec		
Corrective Action:		Date:	

Overall Good: ☒

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Sign at lease road entrance		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Adequate

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	TANK BATTERY		
Comment:	4 strand barbed wire		
Corrective Action:		Date:	
Type	IGNITOR/COMBUSTOR		
Comment:	Corral fencing around both ECD's		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Rod iron		
Corrective Action:		Date:	
Type	SEPARATOR		

Comment:	4 strand barbed wire		
Corrective Action:		Date:	
Type	LOCATION		
Comment:	Electric 4 strand drop fence at lease road entrance		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Emission Control Device	# 2		
Comment:	2 60" ECD's w/ cimmaron ignitors		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:	Glycol unit		
Corrective Action:		Date:	
Type: Bird Protectors	# 3		
Comment:	2 on ECD's and 1 on separator exhaust		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:	PCS control, surface casing plumbed to surface.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:	Date:				

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:	Date:			

**Venting:**

Yes/No		
Comment:		

Corrective Action:		Date:	
<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**Facility ID: 203827 Type: WELL API Number: 001-09387 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
667601590	Location Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4132656">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4132656</a>