



**Photo 1:** View of the project area from the southeastern corner facing center.



**Photo 2:** View of the eastern portion of the project area from the southeastern corner facing northward. There is little to no successful revegetation within the interim reclamation area.



**Photo 3: View of the southern portion of the project area from the southwestern corner facing eastward.**



**Photo 4: View of erosional channel forming within the southern portion of the project area.**



**Photo 5: View of vegetation transect within the eastern portion of the project area. No desirable vegetation was documented along the vegetation transect.**



**Photo 6: Birdseye view of musk thistles within the southeastern portion of the project area.**