



Photo 1: View of the project area from the southeastern corner facing center.



Photo 2: View of the eastern portion of the project area from the southeastern corner facing northward. Revegetation is grazed and largely comprised of crested wheatgrass (*Agropyron cristatum*). Other species were not identifiable.



Photo 3: View of the southern portion of the project area from the southeastern corner facing westward.



Photo 4: View of the northern portion of the project area from the northeastern edge facing westward.



Photo 5: View of erosional channel at culvert along access. Erosion is approximately 2 feet deep and 3 feet wide. Needs to be stabilized.