

Reference Area Photographs

**Inspection Conducted on April 20, 2017
In Response to Complaint #200441313**

**Encana
GMR #34
Grass Mesa Ranch
Location Facility ID # 335102**



Mr. Rodriguez Home – Complaint #200441313 - Looking southeast



Water well Permit #36551 ((1999). Well was perforated to a depth of 160 feet. Looking west from the same location of photo above.



Taking samples from the water well. Looking northwest. Distance from the water well to closest Encana well on Location #335102 is about 600 feet.



Water well close-up



Facilities on Pad Location ID #335102) – Separators, tanks, meter house. Looking southwest. No staining, no junk, good housekeeping.




Inspecting well heads. Bradenhead pressure zero on all wells. No staining observed. Looking east-southeast.




Four Condensate/Produced Water tanks (500 bbls each). Signs in place. Lined secondary containment.



No signs of staining within the secondary containment.



BART analysis for slime and iron bacteria. Very light yellow color observed on the iron sample, 2 hours after sample was taken.



BART analysis for slime and iron bacteria. Yellow color observed on the iron sample after 6 days. Actual color is lighter than photo. Cloudy water on the slime sample.