

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/11/2017

Submitted Date:

04/21/2017

Document Number:

680601458**FIELD INSPECTION FORM**

Loc ID 333470 Inspector Name: ROY, CATHERINE On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 10000Name of Operator: BP AMERICA PRODUCTION COMPANYAddress: 380 AIRPORT RDCity: DURANGO State: CO Zip: 81303**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**5 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email               | Comment                         |
|--------------|-------|---------------------|---------------------------------|
| ,            |       | SanJuanCOGCC@bp.com | <a href="#">All Inspections</a> |
| Beebe, Sabre |       | Sabre.Beebe@bp.com  | <a href="#">All Inspections</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name         | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------------|-------------|
| 258186      | WELL | PR     | 10/06/2000  | GW         | 067-08331 | TURNER SECURITIES A 2 | RI          |
| 292286      | WELL | PR     | 09/17/2007  | GW         | 067-09393 | TURNER SECURITIES A 4 | RI          |

**General Comment:**

[This is an interim reclamation and stormwater inspection. Any corrective actions not addressed from previous inspections are still applicable.](#)

| Inspected Facilities |               |       |             |             |                  |         |           |               |           |
|----------------------|---------------|-------|-------------|-------------|------------------|---------|-----------|---------------|-----------|
| Facility ID:         | <u>258186</u> | Type: | <u>WELL</u> | API Number: | <u>067-08331</u> | Status: | <u>PR</u> | Insp. Status: | <u>RI</u> |
|                      |               |       |             |             |                  |         |           |               |           |
| Facility ID:         | <u>292286</u> | Type: | <u>WELL</u> | API Number: | <u>067-09393</u> | Status: | <u>PR</u> | Insp. Status: | <u>RI</u> |
|                      |               |       |             |             |                  |         |           |               |           |

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: Project area is surrounded by a mixed pinion juniper and oak foothill woodland. A reference area assessment was conducted during this inspection and the results are provided with the inspection photos. Revegetation is progressing within the interim reclamation areas.

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

1002b. SOIL REMOVAL AND SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

1003a. Waste and Debris removed? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

Unused or unneeded equipment onsite? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

|   |   |
|---|---|
| 1003b. Area no longer in use? _____ In _____  | Production areas stabilized ? _____ In _____  |
| 1003c. Compacted areas have been cross ripped? _____  |   |
| 1003d. Drilling pit closed? _____   | Subsidence over on drill pit? _____   |
| Cuttings management: _____  |   |
| 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____ In _____ |   |
| Production areas have been stabilized? _____  | Segregated soils have been replaced? _____  |
| <b>RESTORATION AND REVEGETATION</b>   |   |
| <u>Cropland</u>   |   |
| Top soil replaced _____   | Recontoured _____ Perennial forage re-established _____   |
| <u>Non-Cropland</u>   |   |
| Top soil replaced _____   | Recontoured _____ 80% Revegetation _____ In _____   |
| 1003e. INTERIM VEGETATION TRANSECT  |   |
| TRANSECT RESULTS OF DISTURBED AREA% _____   |   |
| TRANSECT RESULTS OF REFERENCE AREA% _____   |   |
| TOTAL % OF DESIRABLE VEGETATION COVER _____   |   |
| VEGETATIVE COVER _____  |   |
| 1003 f. Weeds Noxious weeds? _____ I _____  |   |
| Comment   | <div style="border: 1px solid black; height: 20px;"></div>  |
| Corrective Action   | <div style="border: 1px solid black; height: 20px;"></div> Date _____                                 |
| Overall Interim Reclamation      In Process   |   |
| <b><u>Final Reclamation/ Abandoned Location:</u></b>  |   |
| Date Final Reclamation Started: _____   | Date Final Reclamation Completed: _____   |
| Final Land Use: _____   |   |
| Reminder: _____   |   |
| Comment: <div style="border: 1px solid black; height: 20px;"></div>   |   |
| Well plugged _____  | Pit mouse/rat holes, cellars backfilled _____   |
| Debris removed _____  | No disturbance /Location never built _____  |
| Access Roads      Regraded _____  | Contoured _____ Culverts removed _____  |
| Gravel removed _____  |   |
| Location and associated production facilities reclaimed _____   | Locations, facilities, roads, recontoured _____   |
| Compaction alleviation _____  | Dust and erosion control _____  |
| Non cropland: Revegetated 80% _____   | Cropland: perennial forage _____  |
| Weeds present _____   | Subsidence _____  |
| 1004.d. FINAL VEGETATION TRANSECT   |   |
| TRANSECT RESULTS OF DISTURBED AREA% _____   |   |
| TRANSECT RESULTS OF REFERENCE AREA% _____   |   |
| TOTAL % OF DESIRABLE VEGETATION COVER _____   |   |
| VEGETATIVE COVER _____  |   |
| Comment:  | <div style="border: 1px solid black; height: 20px;"></div>  |
| Corrective Action:  | <div style="border: 1px solid black; height: 20px;"></div> Date _____                                 |
| Overall Final Reclamation _____   | Well Release on Active Location <input type="checkbox"/> Multi-Well Location <input type="checkbox"/> |

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
|                  |                 |                         |                       |               |                          |         |

Comment: An erosional channel approximately 2 feet wide and 1 foot deep is present in the western portion of the project area.

Corrective Action: Stormwater controls need to be installed to stabilize erosion within the western portion of the project area.

Date: 05/31/2017

Pits: ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 401264842    | INSPECTION SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4129235">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4129235</a> |
| 680601460    | Inspection Photos    | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4129211">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4129211</a> |