

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/21/2017

Submitted Date:

04/24/2017

Document Number:

685302757

FIELD INSPECTION FORM

Loc ID 306808 Inspector Name: St John, William (Cal) On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10000
Name of Operator: BP AMERICA PRODUCTION COMPANY
Address: 380 AIRPORT RD
City: DURANGO State: CO Zip: 81303

Findings:

- 6 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Beebe, Sabre	970-375-7530	Sabre.Beebe@bp.com	SW Inspection Reports
Inspections, All		SanJuanCOGCC@bp.com	SW Inspection Reports

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
268126	WELL	PR	03/12/2010	GW	067-08808	SPANISH FORK B 2	PR

General Comment:

[See link at end of report for path to downloadable pictures.](#) [See Stormwater section of report for additional clarification from previous inspection report.](#)

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Corrective action completed.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	<input type="text"/>	Date:	
Corrective Action:	<input type="text"/>		

Good Housekeeping:

Type	OTHER		
Comment:	Stained soils - Corrective action completed.		
Corrective Action:		Date:	

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 268126 Type: WELL API Number: 067-08808 Status: PR Insp. Status: PR

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Previous inspection misidentified direction of erosion channel as NW corner instead of NE corner. Erosion channel 2"-4" deep and 6"-8" wide in NE corner of location. Similar issue noted in previous inspection. Additional damage done to interim reclamation area by vehicle tracking into that same NE corner.

Corrective Action: Install or repair required BMPs to comply with Rule 1002.f. Refer to the 1002.f guidance document for further details.

Date: 05/25/2017

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401266586	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4131017
685302794	Wellhead sign.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4130762
685302795	Cleaned up wellhead area 1.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4130763
685302796	Cleaned up wellhead area 2.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4130764
685302797	Cleaned up area at muffler.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4130765
685302798	Vehicle tracking in NE corner.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4130766
685302799	Erosion channel in NE corner 1.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4130767
685302800	Erosion channel in NE corner 2.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4130768