

FORM
INSPRev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/21/2017

Submitted Date:

04/24/2017

Document Number:

685302759

FIELD INSPECTION FORM

Loc ID 334057 Inspector Name: St John, William (Cal) On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 56680
 Name of Operator: MERRION OIL & GAS CORP
 Address: 610 REILLY AVENUE
 City: FARMINGTON State: NM Zip: 87401

Findings:

6 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Thompson, Philana	(505) 324-5300	pthompson@merrion.bz	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
284872	WELL	PR	01/01/2016	GW	067-09173	ANTARES 1	PR
292046	WELL	PR	10/15/2007	GW	067-09388	SHAULA 1	PR

General Comment:

[See link at end of report for path to downloadable pictures.](#)

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type OTHER

Comment: [Stained soil - Corrective action completed.](#)

Corrective Action:

Date:

Overall Good:

Spills:

Type	Area	Volume

In Containment: No

Comment:

Multiple Spills and Releases?

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	Open Top		,
Comment: 45 BBL open top tank with steel mesh top.					
Corrective Action: <input type="text"/>					Date: <input type="text"/>

Paint

Condition Adequate

Other (Content)

Other (Capacity) 45 BBLs

Other (Type)

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment: Corrective action completed.				
Corrective Action: <input type="text"/>				Date: <input type="text"/>

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type <input type="text"/>	<input type="text"/>
Comment: <input type="text"/>	<input type="text"/>
Corrective Action: <input type="text"/>	Date: <input type="text"/>

Inspected Facilities

Facility ID: 284872 Type: WELL API Number: 067-09173 Status: PR Insp. Status: PR

Facility ID: 292046 Type: WELL API Number: 067-09388 Status: PR Insp. Status: PR

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	Berms around tank.
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401266589	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4131019
685302804	Wellhead sign for 067 09173.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4130772
685302805	Wellhead sign for 067 09388.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4130773
685302806	Cleaned up soil and gravel.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4130774
685302807	Tank with berms.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4130775