



Photo 1: View of the project area from the southwestern corner facing center.



Photo 2: View of the western portion of the project area from the southwestern edge facing southward. Revegetation is sparse in this area and needs to be monitored and re-seeded in fall 2017 if vegetative cover is not increasing.



Photo 3: View of the eastern portion of the project area from the northeastern corner facing southward. Revegetation is progressing in this area.



Photo 4: View of deep rutting and damaged vegetation from truck tires at the well pad entrance. This area needs stabilization.