

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/27/2017

Submitted Date:

05/02/2017

Document Number:

680301916

FIELD INSPECTION FORM

Loc ID 312138 Inspector Name: SCHURE, KYM On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10548
Name of Operator: HRM RESOURCES II LLC
Address: 410 17TH STREET #1600
City: DENVER State: CO Zip: 80202

Findings:

8 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Dillard, Lea	303-339-8600	l.dillard@hrmres.com	303-893-6621

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
218713	WELL	PR	04/26/2007	OW	075-05445	FRASCO 1-B	PA

General Comment:

[P&A Day \(2\)](#) Upon completion of P&A contact COGCC Reclamation Group and COGCC Environmental Group for directives and approvals.

Location

Lease Road:

Type	Access		
comment:	Upon completion of P&A begin reclamtion process. Contact COGCC Reclamation Group for directives and approval.		
Corrective ActionL		Date:	

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Upon completion of P&A replace signage at wellhead until final approval of reclamation is attained.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	Satisfactory		
Corrective Action:		Date:	_____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment: _____

Multiple Spills and Releases?

Equipment:

				corrective date
Type: Other	#			
Comment:	Equipment remains on-site. Upon completion of P&A remove all equipment and begin reclamation process.			
Corrective Action:		Date:		

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 218713 Type: WELL API Number: 075-05445 Status: PR Insp. Status: PA

Cement

Cement Contractor

Contractor Name: Ranger

Contractor Phone: 713-935-8900

Surface Casing

Cement Volume (sx): _____

Circulate to Surface: _____

Cement Fall Back: _____

Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____

Good Return During Job: _____

Production Casing

Cement Volume (sx): _____

Good Return During Job: _____

Plugging Operations

Depth Plugs(feet range): _____

Cement Volume (sx): _____

Good Return During Job: _____

Cement Type: _____

Comment: P&A Day (2) Stand TBG, discovered damaged (holes) in TBG. Recovered 174 jts, awaiting wireline availability. Secured location for next day.

Corrective Action:

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	In Process	Other	In Process			

Comment: [Continue stormwater erosion management BMP's until final reclamation approval is attained by COGCC.](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT