

Inspection Photos
Location Name: Rollie J Vincent A1
API: 05-123-12556



Photo from prior inspection for comparison purposes



Photo 1: Fencing repaired

Inspection Photos
Location Name: Rollie J Vincent A1
API: 05-123-12556



Photo from prior inspection for comparison purposes



Photo 2: Stained soil at wellhead removed, stained soil near wellhead.

Inspection Photos
Location Name: Rollie J Vincent A1
API: 05-123-12556



Photo from prior inspection for comparison purposes



Photo 3: Unused fencing removed

Inspection Photos
Location Name: Rollie J Vincent A1
API: 05-123-12556



Photo from prior inspection for comparison purposes



Photo 4: Stained soil removed, new stained soil at fitting.

Inspection Photos
Location Name: Rollie J Vincent A1
API: 05-123-12556



Photo from prior inspection for comparison purposes



Photo 5: Stained soil removed

Inspection Photos
Location Name: Rollie J Vincent A1
API: 05-123-12556



Photo from prior inspection for comparison purposes



Photo 6: Stained soil removed, new stained soil in separator house