

FORM  
INSPRev  
X/15

## State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/20/2017

Submitted Date:

04/26/2017

Document Number:

674901632

### FIELD INSPECTION FORM

Loc ID 325143 Inspector Name: Hughes, Jim On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 26625  
 Name of Operator: ELM RIDGE EXPLORATION COMPANY LLC  
 Address: 12225 GREENVILLE AVE STE 950  
 City: DALLAS State: TX Zip: 75243-

**Findings:**

9 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Archuleta, Amy		aarchuleta@elmridge.net	<a href="#">SW Inspection Reports</a>
Fischer, Alex		alex.fischer@state.co.us	
Lindeman, Terry	505-632-8048 EXT 210	tlindeman@elmridge.net	<a href="#">SW Inspection Reports</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214117	WELL	PR	10/31/1959	GW	067-05427	JULIAN MVRD UNIT 1	EI

**General Comment:**

On April 20, 2017 COGCC SW EPS Jim Hughes conducted a follow up environmental field inspection of the Elm Ridge Exploration Co. Julian Mesaverde Unit #1. For the most recent field inspection report for this facility, please refer to document #674901491.

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:	Free standing sign near well head.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Produced water tank has label and placard.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:  Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type	#		corrective date
Ancillary equipment	# 1		
Comment:	Drop out filter and domestic tap.		
Corrective Action:		Date:	
Horizontal Separator	# 1		
Comment:			
Corrective Action:		Date:	
Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Deadman # & Marked	# 3		
Comment:	SE marker has been knocked over.		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLS	STEEL AST		37.106348,-107.763166
Comment:					
Corrective Action:		Date:			

**Paint**

Condition

Other (Content)

Other (Capacity) 10 bbl.	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

**Venting:**

Yes/No			
Comment:			
Corrective Action:			Date:

**Flaring:**

Type			
Comment:			
Corrective Action:			Date:

**Inspected Facilities**

Facility ID: 214117 Type: WELL API Number: 067-05427 Status: PR Insp. Status: EI

### Reclamation - Storm Water - Pit

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment: CA from inspection document #674901491 regarding storm water erosional channel has been addressed.

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

### COGCC Comments

Comment	User	Date
<p>On April 20, 2017 COGCC SW EPS Jim Hughes conducted a follow up environmental field inspection of the Elm Ridge Exploration Co. Julian Mesaverde Unit #1. For the most recent field inspection report for this facility, please refer to document #674901491. The storm water erosional channel on location has been addressed. The SE rig anchor marker has fallen over.</p>	hughesj	04/26/2017

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401267721	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4132339">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4132339</a>
674901633	Storm water erosional channel has been addressed.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4132323">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4132323</a>
674901634	SE rig anchor marker has fallen over.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4132324">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4132324</a>