



**photo 1:** Well casing at the location.



**photo 2:** View of casing which looks to be cemented.





**photo 3:** Facing northeast toward the location. There is various debris which remains.



**photo 4:** Various debris remains.