



Photo 1: View of what appears to be surface owner equipment and debris within the southeastern portion of the project area.



Photo 2: View of more surface owner equipment and debris within the southeastern portion of the project area.



Photo 3: View of exposed soil and erosional channels forming along the southern edge of the access road at the well pad entrance.



Photo 4: View of check dam that is largely full of sediment and needs maintenance.



Photo 5: View of wattles in the southern portion of the project area that are not functioning and need repair or replacement.



Photo 6: View of cobble rundown in the southwestern portion of the project area that is filling with sediment and needs maintenance.