

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/02/2017

Submitted Date:

05/03/2017

Document Number:

674603313**FIELD INSPECTION FORM**Loc ID 429169 Inspector Name: Maclaren, Joe On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10261Name of Operator: BAYSWATER EXPLORATION AND PRODUCTION LLCAddress: 730 17TH ST STE 610City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Hazard, Ellice		ellice.hazard@state.co.us	
Barbula, Don	303-912-4213	dbarbula@bayswater.us	
Miller, Megan		mmiller@bayswater.us	
Allison, Rick		rick.allison@state.co.us	
Blyth, Tom	(303) 893-2503	tblyth@bayswater.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
429168	WELL	SI	02/01/2017	OW	123-35724	SCHNEIDER 16-36	EG
429170	WELL	PR	02/10/2014	OW	123-35725	BALDRIDGE 7-1	EG
429171	WELL	SI	02/01/2017	OW	123-35726	BALDRIDGE 8-1	EG
429172	WELL	PR	01/08/2013	OW	123-35727	SCHNEIDER 37-36	EG
429173	WELL	PR	01/09/2013	OW	123-35728	BALDRIDGE 1-1	EG
429174	WELL	PR	11/01/2013	OW	123-35729	BALDRIDGE 2-1	EG
429175	WELL	PR	01/07/2013	OW	123-35730	BALDRIDGE 17-1	EG
429176	WELL	PR	02/13/2014	OW	123-35731	SCHNEIDER 20-36	EG

General Comment:

COGCC Engineering Integrity Inspection performed on May 2nd, 2017 in response to initial form 19 spill report Doc #401265919 received on 04/26/2017 that outlines: A separator rupture disc malfunctioned and sprayed oil to the West towards the house adjacent to the facility. It is estimated that the wind blew between 5 and 7 bbls of oil over a small field of grass/marshy area. The details of observations made during this field inspection are available in the equipment section of this report. Photo's uploaded can be accessed via link(s) at the end of this report.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

			corrective date
Type: Horizontal Heated Separator	#		
Comment:	Spill response efforts were completed prior to this field inspection. Remediation activities are in progress. There were no Bayswater employees or contractors on site at the time of this field inspection. Note: Document and retain records of root cause of failure evaluation, measures taken to prevent the problem from reoccurring and description of all equipment repairs completed; Indicate which wells are serviced by the faulty/ repaired equipment (*add this information on to the supplemental form 19); Confirm integrity of repairs completed prior to returning equipment to service.		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: <u>429168</u>	Type: <u>WELL</u>	API Number: <u>123-35724</u>	Status: <u>SI</u>	Insp. Status: <u>EG</u>
Facility ID: <u>429170</u>	Type: <u>WELL</u>	API Number: <u>123-35725</u>	Status: <u>PR</u>	Insp. Status: <u>EG</u>
Facility ID: <u>429171</u>	Type: <u>WELL</u>	API Number: <u>123-35726</u>	Status: <u>SI</u>	Insp. Status: <u>EG</u>
Facility ID: <u>429172</u>	Type: <u>WELL</u>	API Number: <u>123-35727</u>	Status: <u>PR</u>	Insp. Status: <u>EG</u>
Facility ID: <u>429173</u>	Type: <u>WELL</u>	API Number: <u>123-35728</u>	Status: <u>PR</u>	Insp. Status: <u>EG</u>
Facility ID: <u>429174</u>	Type: <u>WELL</u>	API Number: <u>123-35729</u>	Status: <u>PR</u>	Insp. Status: <u>EG</u>
Facility ID: <u>429175</u>	Type: <u>WELL</u>	API Number: <u>123-35730</u>	Status: <u>PR</u>	Insp. Status: <u>EG</u>
Facility ID: <u>429176</u>	Type: <u>WELL</u>	API Number: <u>123-35731</u>	Status: <u>PR</u>	Insp. Status: <u>EG</u>

COGCC Comments

Comment	User	Date
	maclarej	05/03/2017

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674603314	Signage at battery	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4138157
674603315	Separators on location	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4138158
674603316	Stormwater/ booms on pad and adjacent property	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4138159