

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/01/2017

Submitted Date:

05/03/2017

Document Number:

685302904**FIELD INSPECTION FORM**Loc ID 325572 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10000Name of Operator: BP AMERICA PRODUCTION COMPANYAddress: 380 AIRPORT RDCity: DURANGO State: CO Zip: 81303**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
- 
- ☒
- FOLLOW UP INSPECTION REQUIRED
- 
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**7 Number of Comments1 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Beebe, Sabre	970-375-7530	Sabre.Beebe@bp.com	<a href="#">SW Inspection Reports</a>
Inspections, All		SanJuanCOGCC@bp.com	<a href="#">SW Inspection Reports</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215026	WELL	PR	12/20/1982	GW	067-06631	CARLSON 32-01 1	PR

**General Comment:**[See link at end of report for path to downloadable pictures.](#)

**Location**Overall Good: ☐**Signs/Marker:**

Type	CONTAINERS		
Comment:	Corrective action completed.		
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:		Date: _____
Corrective Action:		

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	Track pads left on SE corner of location. Corrective action not completed. Corrective action date remains the same to document days of noncompliance.		
Corrective Action:	Remove unused equipment to comply with Rule 603.f using the Rule 603.f guidance document for further details.		Date: 04/17/2017

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	215026	Type:	WELL	API Number:	067-06631	Status:	PR	Insp. Status:	PR

--

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Culverts	Pass			
Check Dams	Pass					
Berms	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	Lube oil tank on spill prevention.

Comment: [Corrective action completed.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685302930	Wellhead sign.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4138176">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4138176</a>
685302931	Track pads in SE corner.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4138177">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4138177</a>
685302932	Repaired rilling on cut slope.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4138178">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4138178</a>
685302933	Replaced NFPA label on lube oil tank.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4138179">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4138179</a>