



**photo 1:** Facing west along main road at approximate Lat/Long: 37.22886,-104.94239. A boulder has fallen near the side of the road which will restrict stormwater flow.



**photo 2:** The gravel has been scrapped of the road and there is little gravel that remains at this area along the main road at approximate Lat/Long:37.22886,-104.94272.



**photo 3:** Approximate Lat/Long:37.22630,-104.94464. Stormwater is flowing and pooling on the road in the direction of the red arrow. The diversion ditch along the side of the road is filled in and not draining as it should in the direction shown by the yellow arrow.



**photo 4:** Approximate Lat/Long:37.22408,-104.94292. Vehicles are creating disturbance outside of the access road.



**photo 5:** Approximate Lat/Long:37.22408,-104.94292. Sediment has filled into the drainage ditch which is not allowing stormwater to flow toward the culvert.



**photo 6:** Facing east at approximate Lat/Long:37.22408,-104.94292.



**photo 7:** Facing northwest toward the Talon site.



**photo 8:** Well sign.