



**Photo 1: View of the project area from the northwestern corner facing center.**



**Photo 2: View of the western portion of the project area from the northwestern corner facing southward. The majority of the project area is devoid of vegetation.**



**Photo 3: View of the northern portion of the project area from the northwestern corner facing eastward.**



**Photo 4: View of surrounding field from the southern edge of the project area facing southward.**





**Photo 5: View of stormwater erosion in the eastern portion of the project area from the eastern edge facing westward.**



**Photo 6: Another view of erosion within the eastern portion of the project area from the eastern edge facing westward.**