

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/02/2017

Submitted Date:

05/03/2017

Document Number:

685302907

FIELD INSPECTION FORM

Loc ID 325409 Inspector Name: St John, William (Cal) On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10000
Name of Operator: BP AMERICA PRODUCTION COMPANY
Address: 380 AIRPORT RD
City: DURANGO State: CO Zip: 81303

Findings:

- 5 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

| Contact Name | Phone | Email | Comment |
|------------------|--------------|---------------------|---------------------------------------|
| Beebe, Sabre | 970-375-7530 | Sabre.Beebe@bp.com | SW Inspection Reports |
| Inspections, All | | SanJuanCOGCC@bp.com | SW Inspection Reports |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 214726 | WELL | PR | 02/01/2017 | GW | 067-06330 | SHARP 1E | PR |

General Comment:

[See link at end of report for path to downloadable pictures.](#)

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

| Type | Area | Volume | | | |
|------|------|--------|--|--|--|
| | | | | | |

In Containment: No

Comment:

Multiple Spills and Releases?

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--|---|----------|-----------|---------|--------|
| PRODUCED WATER | 1 | OTHER | PBV STEEL | | , |
| Comment: New tank. Ols open top has been replaced. | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | |
|------------------|----------|
| Condition | Adequate |
| Other (Content) | |
| Other (Capacity) | 95 BBLs |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|---|----------|---------------------|---------------------|-------------|
| Earth | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: Corrective action completed. | | | | |
| Corrective Action: | | | | Date: |

Venting:

| | |
|--------------------|-------|
| Yes/No | |
| Comment: | |
| Corrective Action: | Date: |

Flaring:

| | |
|--------------------|-------|
| Type | |
| Comment: | |
| Corrective Action: | Date: |

Inspected FacilitiesFacility ID: 214726 Type: WELL API Number: 067-06330 Status: PR Insp. Status: PR**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------------------|---|
| 685302942 | Wellhead sign. | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4139512 |
| 685302943 | New tank with repaired berms. | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4139513 |
| 685302944 | Repaired berms. | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4139514 |
| 685302945 | Location overview. | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4139515 |