

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/02/2017

Submitted Date:

05/03/2017

Document Number:

685302911

FIELD INSPECTION FORM

Loc ID 333801 Inspector Name: St John, William (Cal) On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 55575
Name of Operator: MCELVAIN ENERGY INC
Address: 1050 17TH ST STE 2500
City: DENVER State: CO Zip: 80265-

Findings:

- 4 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|--------------|--------------------------|---------------------------------------|
| Cooper, Tony | 303-893-0933 | tony.cooper@mcelvain.com | SW Inspection Reports |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 274482 | WELL | PR | 04/10/2006 | GW | 067-08985 | SLUGGER 1 | PR |
| 412373 | WELL | PR | 06/02/2010 | GW | 067-09751 | SLUGGER 11 | PR |

General Comment:

[See link at end of report for path to downloadable pictures.](#)

Location

Overall Good:

Signs/Marker:

| | | | |
|--------------------|------------------------------|-------|--|
| Type | TANK LABELS/PLACARDS | | |
| Comment: | Corrective action completed. | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

| | | | |
|--------------------|----------------------|-------|--|
| Comment: | <input type="text"/> | Date: | |
| Corrective Action: | <input type="text"/> | | |

Good Housekeeping:

| | | | |
|--------------------|------------------------------|-------|--|
| Type | UNUSED EQUIPMENT | | |
| Comment: | Corrective action completed. | | |
| Corrective Action: | | Date: | |

Overall Good:

Spills:

| Type | Area | Volume | | |
|------|------|--------|--|--|
| | | | | |

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

| | | | |
|--------------------|--|-------|--|
| Yes/No | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | | |
|--------------------|--|-------|--|
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Inspected FacilitiesFacility ID: 274482 Type: WELL API Number: 067-08985 Status: PR Insp. Status: PRFacility ID: 412373 Type: WELL API Number: 067-09751 Status: PR Insp. Status: PR**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|---|---|
| 685302955 | Wellhead sign for 067-08985. | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4139525 |
| 685302956 | Slugger 1 produced water tank signage. | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4139526 |
| 685302957 | Area where solar panel array was located. | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4139527 |
| 685302958 | Wellhead sign for 067-09751. | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4139528 |
| 685302959 | Slugger 11 produced water tank signage. | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4139529 |
| 685302960 | Wellhead for Slugger 11 cleaned up. | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4139530 |