

# Construction and Stormwater Inspection

May 2, 2017

Operator: ENERPLUS RESOURCES (USA) CORPORATION - #10177

Location ID: 449800

Weld County, CO

SESW Section 36 T8N R67W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: MAPLE #8-67-36-25C  
Location ID: 449800



**Photo 1.** Photo taken from the northeast perimeter of the location, facing South. Ditch and berm BMP has been installed around the entire perimeter of the location.



**Photo 2.** Photo taken from the northeast perimeter of the location, facing West. Ditch and berm BMP has been installed around the entire perimeter of the location.

Inspection Photos  
Location Name: MAPLE #8-67-36-25C  
Location ID: 449800



**Photo 3.** Photo taken from the northeastern location, facing South. Sediment trap has been installed and appears to be in the completion process.



**Photo 4.** Photo taken from the sediment trap, facing North. Stabilized outlet protection has been installed.

Inspection Photos  
Location Name: MAPLE #8-67-36-25C  
Location ID: 449800



**Photo 5.** Photo taken from the northwest perimeter of the location, facing South. Ditch and berm BMP has been installed around the entire perimeter of the location.



**Photo 6.** Photo taken from the western location, facing South towards the topsoil stockpile.

Inspection Photos  
Location Name: MAPLE #8-67-36-25C  
Location ID: 449800



**Photo 7.** Photo taken from the southwest perimeter of the location, facing East. Ditch and berm BMP has been installed around the entire perimeter of the location.



**Photo 8.** Photo taken from the entrance of location, facing East. Sediment trap has been installed and appears to be in the completion process.

Inspection Photos  
Location Name: MAPLE #8-67-36-25C  
Location ID: 449800



**Photo 9.** Photo taken from the sediment trap, facing South. Stabilized outlet protection has been installed.



**Photo 10.** Photo taken from the entrance of location, facing East. Culvert has been installed in conjunction with the ditch and berm BMP.

Inspection Photos  
Location Name: MAPLE #8-67-36-25C  
Location ID: 449800



**Photo 11.** Photo taken from the southeast perimeter of the location, facing North. Ditch and berm BMP has been installed around the entire perimeter of the location.



**Photo 12.** Photo taken from the north side along a portion of the access road, facing East. Diversion ditch has been installed along both sides of the access road.

Inspection Photos  
Location Name: MAPLE #8-67-36-25C  
Location ID: 449800



**Photo 13.** Photo taken from the south side along a portion of the access road, facing East. Diversion ditch has been installed along both sides of the access road.



**Photo 14.** Photo taken from the start of the access road off CR 86 & CR 25, facing West. Construction of the access road is still IN-PROCESS.