

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/24/2017

Submitted Date:

04/24/2017

Document Number:

679700428

**FIELD INSPECTION FORM**

Loc ID 429169 Inspector Name: ALLISON, RICK On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10261  
Name of Operator: BAYSWATER EXPLORATION AND PRODUCTION LLC  
Address: 730 17TH ST STE 610  
City: DENVER State: CO Zip: 80202

**Findings:**

- 4 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Miller, Meagan	832-746-8446	mmiller@bayswater.us	
Barbula, Don	303-912-4213	dbarbula@bayswater.us	
Axelson, John		john.axelson@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
429170	WELL	PR	02/10/2014	OW	123-35725	BALDRIDGE 7-1	EI

**General Comment:**

[COGCC Environmental Inspection for spill reported to COGCC on 4/22/2017](#)

**Inspected Facilities**

Facility ID: 429170 Type: WELL API Number: 123-35725 Status: PR Insp. Status: EI

**Environmental**

**Waste Management:**

Type	Management	Condition	GPS (Lat)	(Long)
Oily Soil	Piles			
Comment	A 4-6 cubic yard stockpile of impacted pad road base was stockpiled within a temporary earthen containment berm.			
Corrective Action				Date:

**Spill/Remediation:**

Comment:	COGCC met Operator onsite in response to spill that occurred the evening of 4/21/2017 and was reported to COGCC on 4/22/2017. Operator stated that a neighbor called the emergency line to inform Operator of the release. That same neighbor called a previous employee of Operator, who then contacted the pumper. Operator indicated that Severance Fire Department also responded and monitored the location during initial cleanup and response, but Operator is unsure who contacted the Fire Department. Separator disc had ruptured releasing oil/condensate from the pad to the west across a grass pasture just upgradient of drain tile discharge area. COGCC did not observe impacts to surface water. Vegetation upgradient of surface water was impacted. Soil beneath the vegetation did not appear impacted. Operator stated that a residence approximately 450 feet west of the release point was impacted and had been washed. Operator is communicating with resident. Operator has placed absorbent booms downgradient of vegetation and in the drain tile discharge area and was monitoring for a sheen. Operator stated that no sheen has been observed. COGCC did not observe a sheen or liquid hydrocarbons on or near the surface water and drain tile discharge area during the inspection.		
Corrective Action:	Operator is directed to continue to remove impacts from the vegetated area and the residence to the west in a timely manner to prevent precipitation or stormwater from impacting downgradient surface water. Corrective Action Date in this inspection is the inspection date to indicate the need for immediate and continued response to remove the impacts. Operator is directed to report all corrective actions through the eForm 19 Spill Report.	Date:	04/24/2017

Emission Control Burner (ECB):	_____
Comment:	_____
Pilot:	Wildlife Protection Devices (fired vessels): _____

**COGCC Comments**

Comment	User	Date
Edited comment regarding who made notifications to Operator and Fire Department regarding spill discovery	allisonr	05/04/2017

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401266396	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4130866">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4130866</a>
679700429	Impacted pasture from pad looking west	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4130708">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4130708</a>
679700430	Storm water ponded in containment on pad	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4130709">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4130709</a>
679700431	Oily waste stockpile	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4130710">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4130710</a>
679700432	Impacted pasture from west looking east	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4130711">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4130711</a>
679700433	Drain tile discharge ppint	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4130712">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4130712</a>