



photo 1: Facing north along the access road.



photo 2: Facing north along the access road near the location.



photo 3: The culvert at the location has been maintained and areas of the pad were seeded and mulched.



photo 4: Facing northwest toward the location.



photo 5: The sediment trap at the southwest side has been maintained.



photo 6: Facing north toward the west cut slope.