

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/03/2017

Submitted Date:

05/03/2017

Document Number:

679700434**FIELD INSPECTION FORM**
 Loc ID 418514 Inspector Name: ALLISON, RICK On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_
**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1625 BROADWAY STE 2200City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**1 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

| Contact Name       | Phone | Email                                  | Comment |
|--------------------|-------|--|---------|
| Inspections, Noble |       | NBL_DJBU_Inspections@NB<br>LENERGY.COM |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 418515      | WELL | PR     | 09/01/2014  | OW         | 123-31940 | DRAKE II18-04 | EI          |

**General Comment:**

**Location**Overall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒**Spills:**

| Type   | Area | Volume   |                  |  |
|--|------|----------|------------------|--|
| Produced Water   | Tank | <= 1 bbl |                  |  |
| Comment: Evidence of produced water vault overflow < 5bbls in lined secondary containment                                    |      |          |                  |  |
| Corrective Action: Implement corrective measures to prevent overflow of produced water vessel. Cleanup oily residue on tank. |      |          | Date: 06/03/2017 |  |

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

| Type                          |     |       | corrective date |
|-------------------------------|-----|-------|-----------------|
| Type: Gas Meter Run           | # 1 |       |                 |
| Comment:                      |     |       |                 |
| Corrective Action:            |     | Date: |                 |
| Type: Bird Protectors         | # 4 |       |                 |
| Comment:                      |     |       |                 |
| Corrective Action:            |     | Date: |                 |
| Type: Emission Control Device | # 2 |       |                 |
| Comment:                      |     |       |                 |
| Corrective Action:            |     | Date: |                 |
| Type: Horizontal Separator    | # 2 |       |                 |
| Comment:                      |     |       |                 |
| Corrective Action:            |     | Date: |                 |

**Tanks and Berms:**

| Contents           | # | Capacity  | Type        | Tank ID | SE GPS |
|--------------------|---|-----------|-------------|---------|--------|
| PRODUCED WATER     | 1 | <100 BBLS | BV CONCRETE |         | ,      |
| Comment:           |   |           |             |         |        |
| Corrective Action: |   |           |             | Date:   |        |

**Paint**

|                  |  |
|------------------|--|
| Condition        |  |
| Other (Content)  |  |
| Other (Capacity) |  |
| Other (Type)     |  |

**Berms**

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|------|----------|---------------------|---------------------|-------------|
|------|----------|---------------------|---------------------|-------------|

Inspector Name: ALLISON, RICK

|                    |          |                  |                 |          |        |
|--------------------|----------|------------------|-----------------|----------|--------|
| Metal              | Adequate | Walls Sufficient | Base Sufficient | Adequate |        |
| Comment:           |          |                  |                 |          |        |
| Corrective Action: |          |                  |                 |          | Date:  |
| Contents           | #        | Capacity         | Type            | Tank ID  | SE GPS |
| CRUDE OIL          | 1        | 300 BBLs         | STEEL AST       |          | ,      |
| Comment:           |          |                  |                 |          |        |
| Corrective Action: |          |                  |                 |          | Date:  |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

**Berms**

|                    |          |                     |                     |             |       |
|--------------------|----------|---------------------|---------------------|-------------|-------|
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |       |
| Metal              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |       |
| Comment:           |          |                     |                     |             |       |
| Corrective Action: |          |                     |                     |             | Date: |

**Venting:**

|                    |  |  |       |
|--------------------|--|--|-------|
| Yes/No             |  |  |       |
| Comment:           |  |  |       |
| Corrective Action: |  |  | Date: |

**Flaring:**

|                    |  |  |       |
|--------------------|--|--|-------|
| Type               |  |  |       |
| Comment:           |  |  |       |
| Corrective Action: |  |  | Date: |

**Inspected Facilities**Facility ID: 418515 Type: WELL API Number: 123-31940 Status: PR Insp. Status: EI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description             | URL   |
|--------------|-------------------------|---|
| 401274266    | INSPECTION<br>SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4138591">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4138591</a> |
| 679700435    | Produced water vessel   | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4138590">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4138590</a> |