

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/03/2017

Submitted Date:

05/04/2017

Document Number:

675103558**FIELD INSPECTION FORM**
 Loc ID 335678 Inspector Name: GRANAHAH, KYLE On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_
**Operator Information:**OGCC Operator Number: 10447Name of Operator: URSA OPERATING COMPANY LLCAddress: 1050 17TH STREET #1700City: DENVER State: CO Zip: 80265**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**7 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Burger, Craig		craig.burger@state.co.us	
Thompson, Bud		BLThomps@BLM.gov	
Lind, Jennifer	(720) 508-8362	jlind@ursaresources.com	<a href="#">All Inspections</a>
Kellerby, Shaun		shaun.kellerby@state.co.us	
Knudson, Dwayne	(970) 456-3335	dknudson@ursaresources.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
449844	WELL	XX	03/31/2017		103-12285	BR C-24O 42D-24-2-98	DG

**General Comment:**[On location to witness surface cement job in regards to form 42 doc #401270979](#)

**Location**Overall Good: ☒**Signs/Marker:**

Type	DRILLING/RECOMP		
Comment:	Complete/present		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	Emergency plan/contacts and cordinates present in company office on location.		
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 449844 Type: WELL API Number: 103-12285 Status: XX Insp. Status: DG

**Cement**Cement ContractorContractor Name: HalliburtonContractor Phone: GrandJunctionSurface CasingCement Volume (sx): 950Circulate to Surface: YESCement Fall Back: YESTop Job, 1" Volume: NOIntermediate Casing

Cement Volume (sxs): \_\_\_\_\_

Good Return During Job: \_\_\_\_\_

Production Casing

Cement Volume (sx): \_\_\_\_\_

Good Return During Job: \_\_\_\_\_

Plugging Operations

Depth Plugs(feet range): \_\_\_\_\_

Cement Volume (sx): \_\_\_\_\_

Good Return During Job: YES

Cement Type: \_\_\_\_\_

Comment:

TD - 3885'  
 Casing TD - 3848'  
 DV stage tool - 2135'  
 Last centralizer ran at - 30'  
 Stage 1 -  
 20 bbls h2o spacer  
 190 bbls 12.5 ppg cement  
 displace with 294 bbls h2o  
 Land plug/check floats - held/drop dv opening tool/ open tool with halliburton truck  
 pump/establish circulation/circulate from dv tool to surface for 5 hrs/pumped bottoms up  
 volume - 27 bbls good cement to surface  
 Cement blend -  
 12.5 ppg  
 1.94 yield  
 10.15 gals h2o/sk  
 60% XS  
 Stage 2 -  
 10 bbls h2o spacer  
 174.5 bbls 12.3ppg cement  
 displace 165 bbls with h2o  
 cement to surface at 145 bbls displacement  
 20 bbls cement to surface  
 land plug/release pressure/ ensure plug holds - plug held/ rig down  
 Check for cement fall back - Cement has fallen - unable to determine top of cement at  
 time of inspection.  
 Cement blend -  
 12.3 ppg  
 2.45 yield  
 14.18 gals h2o/sk  
 75% XS

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass					
				Covering Materials	Pass	
Berms	Pass					
Sediment Traps	Pass					
				Material Handling And Spill Prevention	Pass	

Comment: [No sediment flow evident](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401275288	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4139560">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4139560</a>