

Inspected Facilities

Facility ID: 243734 Type: WELL API Number: 123-11526 Status: PR Insp. Status: PR

Cement

Cement Contractor

Contractor Name: LEED

Contractor Phone: _____

Surface Casing

Cement Volume (sx): _____

Circulate to Surface: _____

Cement Fall Back: _____

Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____

Good Return During Job: _____

Production Casing

Cement Volume (sx): _____

Good Return During Job: _____

Plugging Operations

Depth Plugs(feet range): _____

Cement Volume (sx): _____

Good Return During Job: _____

Cement Type: _____

Comment: LEED Rig 734 on location. Conditioned Annulus Pumped 825 Sxs Thru Retainer. Displaced Tubing. Unable To Sting Out. SWI

Corrective Action:

Date: _____

BradenHead

Comment: Bradenhead is plumed to surface.

Corrective Action:

Date: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401275286	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4139559