



Photo 1: View of the project area from the southwestern corner facing center.



Photo 2: View of the southern portion of the project area from the southwestern corner facing eastward. It appears southern area was recently seeded and mulched. Some germination was observed.



Photo 3: View of the western portion of the project area from the southwestern corner facing northward.



Photo 4: View of the eastern portion of the project area from the southeastern corner facing northward. Two unused ladders are present around the tanks.