

Construction and Stormwater Inspection

May 5, 2017

Operator: BURLINGTON RESOURCES OIL & GAS LP- #26580

Location ID: 443722

Arapahoe County, CO

SWSW Section 2 T4S R65W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Prosper Farms 4-65 2-1 /4AH
Location ID: 443722



Photo 1. Photo taken north of the topsoil stockpile, facing South. A ditch and berm BMP has been installed around the western location of the stockpile which is directed to a stabilized pit. Per conversations with the Operator, this will be directed to the sediment basin upon completion of the location.



Photo 2. Photo taken from the northeastern location, facing North. Sediment basin has been installed with both inlet and outlet protection devices.

Inspection Photos
Location Name: Prosper Farms 4-65 2-1 /4AH
Location ID: 443722



Photo 3. Photo taken from the previous photo location, facing West. A ditch and berm BMP has been installed around the perimeter of the location where stormwater runoff is directed through a culvert to the sediment basin.



Photo 4. Photo taken from the eastern perimeter of the location, facing Southeast. A spoil stockpile has been stored along the eastern perimeter of the location. Per conversations with the Operator, all stockpiles will be seeded, straw mulched and crimped upon completion of the location.

Inspection Photos
Location Name: Prosper Farms 4-65 2-1 /4AH
Location ID: 443722



Photo 5. Photo taken from the top of the spoil stockpile, facing South. Filtrexx wattles have been installed around the outer perimeter of the stockpile. Portions of the filtrex are in need of repair/maintenance. Per conversations with the Operator, all stockpiles will be seeded, straw mulched and crimped upon completion of the location.



Photo 6. Photo taken from the top of the spoil stockpile, facing North. Filtrexx wattles have been installed around the outer perimeter of the stockpile and portions are in need of repair/maintenance. Per conversations with the Operator, all stockpiles will be seeded, straw mulched and crimped upon completion of the location.

Inspection Photos
Location Name: Prosper Farms 4-65 2-1 /4AH
Location ID: 443722



Photo 7. Photo taken from an outlet of a culvert along the east-facing side of the access road, facing South. A stabilized outlet has been installed in conjunction with the culvert.



Photo 8. Photo taken along the north-facing side of the same access road in the previous photo, facing East. A shallow ditch has been constructed and appears to be directed to the stabilized outlet used for the culvert.

Inspection Photos

Location Name: Prosper Farms 4-65 2-1 /4AH

Location ID: 443722



Photo 9. Photo taken from the western access road, facing South. A stabilized outlet has been installed in conjunction with the culvert.



Photo 10. Photo taken from the entrance of location, facing North. A stabilized outlet has been installed in conjunction with the culvert.