

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/10/2017

Submitted Date:

05/11/2017

Document Number:

673504272

**FIELD INSPECTION FORM**

Loc ID 309402 Inspector Name: COSTA, RYAN On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 100264  
Name of Operator: XTO ENERGY INC  
Address: PO BOX 6501  
City: ENGLEWOOD State: CO Zip: 80155

**Findings:**

2 Number of Comments  
1 Number of Corrective Actions

Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
FITZGERALD EDIE		edie_fitzgerald@xtoenergy.com	
Trujillo, Irwin		irwin_trujillo@xtoenergy.com	
Harrison, Lyndon		lyndon_harrison@xtoenergy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
164	WELL	PR	01/21/2009	GW	071-09485	GOLDEN EAGLE 28-01	RI
300259	PIT	AC	12/16/2008		-	GOLDEN EAGLE 28-01	AC

**General Comment:**

[This is an Interim Reclamation and Stormwater Management Inspection.](#)

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: There are areas along the main road and at the location where vehicle rutting and potholes have developed. Ther are signs of erosion along the cut slope of the location. See attached Photos

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 06/16/2017

**Pits:**     NO SURFACE INDICATION OF PIT

Type: Produced Water      Lined: YES      Pit ID: 300259      Lat: 37.148836      Long: -104.886740

Reference Point: \_\_\_\_\_ Other: \_\_\_\_\_ Length: \_\_\_\_\_ Width: \_\_\_\_\_

**Lining:**

Liner Type: \_\_\_\_\_ Liner Condition: Adequate

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: c

**Fencing:**

Fencing Type: Other      Fencing Condition: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Netting:**

Netting Type: \_\_\_\_\_ Netting Condition: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

Anchor Trench Present: \_\_\_\_\_ Oil Accumulation: NO      2+ feet Freeboard: YES

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

Permit:	Facility ID	Permit Num	Expiration Date
	300259	1841334	

Monitoring:	Monitoring Type	Comment
	Chain	

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
673504273	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4145898">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4145898</a>