

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/10/2017

Submitted Date:

05/12/2017

Document Number:

682600300

FIELD INSPECTION FORM

Loc ID 333876 Inspector Name: Kosola, Jason On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10084
Name of Operator: PIONEER NATURAL RESOURCES USA INC
Address: 5205 N O'CONNOR BLVD STE 200
City: IRVING State: TX Zip: 75039

Findings:

- 4 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Axelson, John		john.axelson@state.co.us	
Distribution, Pioneer	972-444-9001	COGCC.Inspections@pxd.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
274310	PIT	AC	10/22/2004		-	FIRE FLY 24-11 KV ONSITE	AC

General Comment:

This is an environmental inspection. Any corrective actions from previous inspections that have not been addressed are still applicable.

COGCC Inspection 673504071 identified a torn pit liner on pit 274310. Pit liner remains compromised and fencing around pit is in disrepair. Operator is not currently using pit for produced water.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	PIT		
Comment:	Fencing around pit is in disrepair (see attached photos).		
Corrective Action:	Net or fence pit to prevent access per rule 902.d.		Date: 05/19/2017

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: Produced Water Lined: YES Pit ID: 274310 Lat: 37.179744 Long: -104.857325

Reference Point: SE Other: _____ Length: _____ Width: _____

Lining:

Liner Type: Plastic Liner Condition: Inadequate

Comment: Liner integrity has been compromised - see attached photos (identified on inspection 673504071 on 2/10/17). Liner integrity remains compromised as of current inspection 5/10/17. Pit is not currently in use for produced water. Water currently in pit is most likely stormwater.

Corrective Action: Lack of pit liner or pit liner compromised (Rule 904). Repair pit liner prior to putting pit back in use. If pit will no longer be used, contact COGCC EPS to begin pit closure procedures.

Date: 05/31/2017c

Fencing:

Fencing Type: _____ Fencing Condition: _____

Comment:

Corrective Action:

Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment:

Corrective Action:

Date: _____

Anchor Trench Present: _____ Oil Accumulation: _____ 2+ feet Freeboard: _____

Comment:

Corrective Action:

Date: _____

Permit:	Facility ID	Permit Num	Expiration Date
	274310	1230419	
	270432	112962	

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
682600301	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4145902