

**Inspection Photos**  
**Location Name: Elkhorn Company B#6**  
**API: 05-123-09488**



**Photo 1: Location, looking SE**



**Photo 2: Wellhead, looking N**

**Inspection Photos**  
**Location Name: Elkhorn Company B#6**  
**API: 05-123-09488**



**Photo from prior inspection for comparison**



**Photo 3: Stained soil removed/remediated**



**Inspection Photos**  
**Location Name: Elkhorn Company B#6**  
**API: 05-123-09488**



**Photo from prior inspection for comparison**



**Photo 4: Stained soil removed/remediated**

**Inspection Photos**  
**Location Name: Elkhorn Company B#6**  
**API: 05-123-09488**



**Photo from prior inspection for comparison**



**Photo 5: Stained soil removed/remediated**



**Inspection Photos**  
**Location Name: Elkhorn Company B#6**  
**API: 05-123-09488**



**Photo from prior inspection for comparison**



**Photo 6: Stained soil removed remediated**

**Inspection Photos**  
**Location Name: Elkhorn Company B#6**  
**API: 05-123-09488**



**Photo from prior inspection for comparison**



**Photo 7: Stained soil at manifold**



**Inspection Photos**  
**Location Name: Elkhorn Company B#6**  
**API: 05-123-09488**



**Photo from prior inspection for comparison**



**Photo 8: Stained soil removed/remediated**

**Inspection Photos**  
**Location Name: Elkhorn Company B#6**  
**API: 05-123-09488**



**Photo from prior inspection for comparison**



**Photo 9: Stained soil removed/remediated**



**Inspection Photos**  
**Location Name: Elkhorn Company B#6**  
**API: 05-123-09488**



**Photo 10: Stormwater erosion on W side of location, looking W**



**Photo 11: Berms trampled by livestock**