

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/08/2017

Submitted Date:

05/08/2017

Document Number:

685302999**FIELD INSPECTION FORM**Loc ID 311904 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 26625Name of Operator: ELM RIDGE EXPLORATION COMPANY LLCAddress: 12225 GREENVILLE AVE STE 950City: DALLAS State: TX Zip: 75243-**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
- 
- ☐
- FOLLOW UP INSPECTION REQUIRED
- 
- ☒
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**6 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Lindeman, Terry	505-632-8048 EXT 210	tlindeman@elmridge.net	<a href="#">SW Inspection Reports</a>
Redmond, Nolan	720-484-2347	Inspections@catamountep.com	<a href="#">All Inspections</a>
Archuleta, Amy		aarchuleta@elmridge.net	<a href="#">SW Inspection Reports</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214350	WELL	PR	02/01/1997	GW	067-05749	V D HELTON 1	PR
216569	WELL	PR	01/15/1999	GW	067-08175	HELTON 1A	PR

**General Comment:**[See link at end of report for path to downloadable pictures.](#)

**Location**Overall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	OTHER	Open Top		37.107589,-107.754173	
Comment: Open top tank with stell mesh top with earthen berms.						
Corrective Action:					Date:	

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)	40 BBLS	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment: Corrective action completed.				
Corrective Action:				Date:

**Venting:**

Yes/No		
Comment:		
Corrective Action:		Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 214350	Type: WELL	API Number: 067-05749	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Facility ID: 216569	Type: WELL	API Number: 067-08175	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401277622	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4142058">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4142058</a>
685303023	Wellhead sign for 067 05749.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4142036">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4142036</a>
685303024	Wellhead sign for 067 08175.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4142037">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4142037</a>
685303025	Location overview with repaired tank berms.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4142038">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4142038</a>