

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/08/2017

Submitted Date:

05/09/2017

Document Number:

673715418**FIELD INSPECTION FORM**Loc ID 436974 Inspector Name: Sherman, Susan On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 96340Name of Operator: WIEPKING-FULLERTON ENERGY LLCAddress: 4600 S DOWNING STCity: ENGLEWOOD State: CO Zip: 80113**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:17 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Herian, Tim	(316) 655-9200	therian1@cox.net	All Inspections
Shalberg, Greg	(719) 688-3547	gregshalberg@aol.com	
Boone, Linda	(720) 271-8605	LDBoonePar@aol.com	All Inspections
Halde, Kerry	(719) 340-0329	haldeoi@hotmail.com	All Inspections
Kosola, Jason		jason.kosola@state.co.us	COGCC EPS
Leonard, Mike		mike.leonard@state.co.us	COGCC QAP

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
436975	WELL	PR	07/15/2014	OW	073-06603	GAEDE A9S-55W-05-43	PR

General Comment:

Location

Overall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 719-688-3547

Corrective Action:

Date: _____

Overall Good: ☐

Spills:			
Type	Area	Volume	
PW/CO	Tank	<= 1 bbl	
Comment:	See attached photos of stained soil inside tank battery berms and outside berms on south side of battery. Contacted Operator who said that cleanup of the tank battery is scheduled. Stained soil inside treater berms at west treater (see attached photo).		
Corrective Action:	Properly treat or dispose of oily waste in accordance with Rule 907.e. Contact area COGCC EPS.		Date: 05/16/2017
Crude Oil	Separator	<= 1 bbl	
Comment:	Oil leak inside treater shed at middle treater (see attached photo).		
Corrective Action:	Properly treat or dispose of oily waste in accordance with Rule 907.e. Contact area COGCC EPS.		Date: 05/16/2017

In Containment: Yes

Comment: Not all stained soil is in containment. Check tank battery liner for integrity on south side of battery.

☒ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	steel panels		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Pump Jack	# 1		

Comment:	chemical container, solar panel		Date:	
Corrective Action:			Date:	
Type: Vertical Heater Treater	# 3			
Comment:	Two in shed, west treater not in operation		Date:	
Corrective Action:			Date:	
Type: Prime Mover	# 1			
Comment:	gas engine		Date:	
Corrective Action:			Date:	
Type: Emission Control Device	# 1			
Comment:	pilot on		Date:	
Corrective Action:			Date:	
Type: Bird Protectors	# 4			
Comment:			Date:	
Corrective Action:			Date:	
Type: Gas Meter Run	# 3			
Comment:	Three sheds, no meter in west shed, meters in middle and east sheds are not on.		Date:	
Corrective Action:			Date:	
Type: Flare	# 2			
Comment:			Date:	
Corrective Action:			Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	4	400 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Inadequate
Comment:	Maintain south and SE berms at ground level. See Spill section for details.			
Corrective Action:	Contact COGCC EPS.			Date: 05/16/2017

Venting:

Yes/No	YES	
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities				
Facility ID: 436975	Type: WELL	API Number: 073-06603	Status: PR	Insp. Status: PR
Producing Well				
Comment:	PR.			
Corrective Action:				Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	
Rip Rap	Pass					
Waddles	Pass	Ditches	Pass			
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Optical Gas Imaging SurveySurvey Type: RoutineCurrent Operations: ☒ Production ☐ Workover ☐ Flowback ☐ Referred to APCD

GPS(entrance of location): Lat: _____ Long: _____

Wind: Light Speed: _____ (mph) Direction From: NW Weather: Clear Temperature: 62 (F)

Assisting Staff: _____ Camera #: _____

☐ Visible Smoke ☐ Referred to CDPHE

Times Surveyed

Equipment Surveyed

Time Survey Start	AM/PM	Time Survey End	AM/PM
0830	AM	0900	AM

Equipment
Separation Equipment
Water Tank(s)

Comment: See Tank Flir file for same small leak from top of NE produced water tank. Operator contacted and said that all parts were replaced.Corrective
Action:

Date:

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401279150	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4143428
673715437	Wiepking Gaede ECD Flir File	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4143418
673715438	Wiepking Gaede Tank Flir File	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4143419
673715439	Wiepking Gaede A9S-55W-05-43	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4143420