

Reclamation Inspection

May 15, 2017

Operator: LONGS PEAK RESOURCES LLC- #10611

Location ID: 440192

Weld County, CO

NENW Section 35 T12N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Pismo East
Location ID: 440192



2015 aerial imagery using COGCC GISOnline database illustrating the Pismo East location in relation to the MLVT location approximately 0.54 miles to the east.

Inspection Photos
Location Name: Pismo East
Location ID: 440192



Google Earth aerial imagery taken September 7, 2016 of the MLVT location overlaid with field collected data using a Trimble handheld GPS from the May 15, 2017 inspection. Aerial imagery illustrates the approximate total disturbance area of the MLVT location highlighted in red and the actual tank location highlighted in orange.

Inspection Photos
Location Name: Pismo East
Location ID: 440192



Photo 1. Photo taken from the center of the tank location, facing West. All disturbance associated with the MLVT location will have to be reclaimed per Rule 1004 standards.



Photo 2. Photo taken from the center of the tank location, facing North. All disturbance associated with the MLVT location will have to be reclaimed per Rule 1004 standards.

Inspection Photos
Location Name: Pismo East
Location ID: 440192



Photo 3. Photo taken from the center of the tank location, facing East. All disturbance associated with the MLVT location will have to be reclaimed per Rule 1004 standards.



Photo 4. Photo taken from the center of the tank location, facing South. All disturbance associated with the MLVT location will have to be reclaimed per Rule 1004 standards.

Inspection Photos
Location Name: Pismo East
Location ID: 440192



Photo 5. Photo taken from the southern disturbance area of the MLVT location, facing East. All disturbance associated with the MLVT location will have to be reclaimed per Rule 1004 standards.



Photo 6. Photo taken from the eastern disturbance area of the MLVT location, facing East. All disturbance associated with the MLVT location will have to be reclaimed per Rule 1004 standards.

Inspection Photos
Location Name: Pismo East
Location ID: 440192



Photo 7. Photo taken from the eastern disturbance area of the MLVT location, facing West. All disturbance associated with the MLVT location will have to be reclaimed per Rule 1004 standards.



Photo 8. Photo taken from the eastern disturbance area of the MLVT location, facing West. All disturbance associated with the MLVT location will have to be reclaimed per Rule 1004 standards.

Inspection Photos
Location Name: Pismo East
Location ID: 440192



Photo 9. Reference photo taken east of the MLVT location area, facing North.