

Inspection Photos

05/16/2017

Operator: Denver East Machinery Co #24040

Location ID: 374981

Inspection Doc. Number: 682502019

Washington County, CO

Aaron Trujillo

Reclamation Specialist

COGCC



Inspection Photos
Operator: Denver East Machinery Co #24040
Location ID: 374981



Photo 1: Photo of GPS verifying location.

Inspection Photos
Operator: Denver East Machinery Co #24040
Location ID: 374981



Photo 2: Photo taken on the well location, facing north. Photo shows vegetation over the reclamation area.



Photo 3: Photo taken on the well location, facing east. Photo shows vegetation over the reclamation area.

Inspection Photos
Operator: Denver East Machinery Co #24040
Location ID: 374981



Photo 4: Photo taken on the well location, facing south. Photo shows vegetation over the reclamation area.



Photo 5: Photo taken on the well location, facing west. Photo shows vegetation over the reclamation area.

Inspection Photos
Operator: Denver East Machinery Co #24040
Location ID: 374981



Photo 5: Photo taken from the battery/pit location, southeast of the well. Photo shows concrete debris still remaining.



Photo 5: Photo taken from the battery/pit location, southeast of the well. Photo shows debris still remaining.

Inspection Photos
Operator: Denver East Machinery Co #24040
Location ID: 374981



Photo 6: Photo taken from the battery/pit location, southeast of the well, facing east. Photo shows large area at the pit and to the east that remains bare and unvegetated. Possibly salt kill.



Photo 7: Photo taken from the battery/pit location, southeast of the well, facing east. Photo shows large area at the pit and to the east that remains bare and unvegetated. Possibly salt kill.

Inspection Photos
Operator: Denver East Machinery Co #24040
Location ID: 374981



Photo 8: Photo taken from the battery/pit location, southeast of the well, facing east. Photo shows large area at the pit and to the east that remains bare and unvegetated. Possibly salt kill. 6 foot measuring stick for reference.



Photo 9: Photo taken from the pit location. Photo shows debris still remaining.

Inspection Photos
Operator: Denver East Machinery Co #24040
Location ID: 374981



Photo 10: Photo taken from the east end of the disturbance area, facing west towards the pit. Possibly a salt kill. Photo shows large areas that area bare and exposed soil



Photo 11: Photo taken from within the alleged salt kill. Photo shows erosion occurring within the disturbance. 6 foot measuring stick for reference.

Inspection Photos
Operator: Denver East Machinery Co #24040
Location ID: 374981



Photo 12: 1998 aerial imagery. Photo shows battery and pit location. Pit in red. Photo also shows a large bare area directly to the east of the well. Bare area likely a salt kill.



Photo 13: 2016 aerial imagery. Photo shows battery and pit location. Pit in red. Photo also shows a large bare area directly to the east of the well. Bare area likely a salt kill. Main bare area seen in yellow ~1 ac in size.