

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/16/2017

Submitted Date:

05/19/2017

Document Number:

674603329

FIELD INSPECTION FORM

Loc ID 428521 Inspector Name: Maclaren, Joe On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 8960
Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY
Address: 410 17TH STREET SUITE #1400
City: DENVER State: CO Zip: 80202

Findings:

- 3 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Chesson, Bob		robert.chesson@state.co.us	
,		EHSRC@bonanzacrk.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
435423	WELL	PR	07/07/2014	OW	123-38606	Park T-P-4HC	EG

General Comment:

COGCC Integrity Inspection performed on May 16th, 2017 in response to initial form 19 spill report Doc #401278434 received on 05/12/2017 that outlines: During routine site inspections on 5/3/2017, an operator noted that a release occurred inside the separator cabinet at the Park T-4. It was discovered that the produced water dumpline was leaking. The release occurred beneath the secondary containment liner. After exposing the line and using a calibrated PID to remove all of the impacted soil the total release volume is estimated to be 19 bbls. Soil samples were taken and will be submitted for laboratory analysis. Once repaired, the line will be pressured tested prior to being put back in service. The details of observations made during this field inspection are available in the flowline section of this report. Photo's uploaded and can be accessed via link(s) at the end of this report.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type	#	corrective date
Flow Line		
Comment: Multiple unused flowline risers observed on this location; Must comply with requirements of COGCC NTO dated 5/2/2017 (as applicable).		
Corrective Action: <input type="text"/>		Date: <input type="text"/>

Venting:

Yes/No		
Comment:		
Corrective Action:		Date: <input type="text"/>

Flaring:

Type	
Comment:	
Corrective Action:	Date: <input type="text"/>

Inspected Facilities

Facility ID: 435423 Type: WELL API Number: 123-38606 Status: PR Insp. Status: EG

Flowline

#1	Type: Dump Line	of Lines
----	-----------------	----------

Flowline Description

Flowline Type: Dump Line Size: _____ Material: Carbon Steel
 Variance: _____ Age: _____ Contents: Produced Water

Integrity Summary

Failures: _____ Spills: Yes Repairs Made: _____
 Coatings: _____ H2S: _____ Cathodic Protection: _____

Pressure Testing

Witnessed: _____ Test Result: _____ Charted: _____

COGCC Rules(check all that apply)

1101. Installation and Reclamation 1102. Operations, Maintenance, and Repair 1103. Abandonment

Comment: Repairs are being completed on the produced water dump flowline(s) at the Park T-4 separator. The dump line is disconnected at this time. Excavation and remediation work observed in progress during this field inspection. Note: Document and retain records of root cause of failure evaluation, measures taken to prevent the problem from reoccurring and description of all flowline repairs completed (on supplemental form 19); perform flowline pressure testing to verify integrity of repairs completed (retain chart & data) prior to returning flowline to service.

Corrective Action: _____

Date: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674603334	Signage at Separators	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4151337
674603335	Remediation/ Dump line repairs in progress	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4151338
674603336	Disconnected unused flowline risers	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4151339
674603337	Disconnected unused risers at separators	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4151340